Inspection Conclusion Data Sheet (ICDS)

Action Type:	SPCC Inspection	Facility ID: R1-ME-00131	Action Date 12/18/2008
EPA Inspector:	Sherrin		
Facility Name:	Down East Energy Springvale		
•	288 River Street		
City:	Springvale	State: ME	ZIP: 04083
Contact Person:			Telephone:
1. Media Type			
✓ CWA	311 (SPCC)		
☐ CWA	311 (FRP)		
CWA	311 (Government-Initiated Una	nnounced Exercise [GIUE])	
2. Did you observ	re deficiencies (potential viola	ations) during the inspection?	
Yes			
3. If you o	observed deficiencies, did yo	u communicate them to the facility dur	ing the inspection?
Y	es		
4. Deficie	ncies observed?		
	Dotential violation of a compl	ance schedule in an enforceable order.	
	Dotential failure to maintain a	record or failure to disclose a document.	
	Dotential failure to maintain, i	nspect or repair equipment including met	ers, sensors, and recording equipment.
	Potential failure to complete	or submit a notification, report, certificatio	n, or manifest.
	Potential failure to obtain a po	ermit, product approval, or certification.	
	Potential failure to follow a re	quired sampling or monitoring procedure	or laboratory procedure.
V	Potential failure to follow or d	evelop a required management practice	or procedure.
	Potential failure to identify an	d manage a regulated waste or pollutant	in any media.
	Potential failure to report regu	ulated events such as spills, accidents, et	c.
	Potential incorrect use of a m material.	aterial (e.g., pesticide, waste, product, et	c.) or use of improper or unapproved
	Potential failure to follow a pe	ermit condition(s).	
	ou observe or see the facility icated to the facility?	take any actions during the inspection	to address the deficiencies
No)		
	YES, check only the action(s) a the "optional" section. (check a	ctually observed/seen or write in a short II that apply)	description of the action
Ac	ction(s) Taken		
	Complete(d) a Notification or	Report.	
	Correct(ed) Monitoring Defici	encies	
	Correct(ed) Record Keeping	Deficiencies	
		ed Management Practices or Procedures	
		ion (e.g., Labeling, Manifesting, Storage,	·
L	_	Reduction, Industrial Process Change, E	missions or Discharge Change, etc.)
L	Request(ed) a Permit Application Verified Compliance with Pre	ation or Applied for a Permit viously Issued Enforcement Action - Part	or All Conditions

Inspection Conclusion Data Sheet (ICDS)

Action Type: SPCC	Inspection	Facility ID: R1-ME-00131	Action Date 12/18/2008	
EPA Inspector: Sherra	in			
Facility Name: Down Address: 288 R City: Spring Contact Person:		State: ME	ZIP: <i>04083</i> Telephone:	
The follo		er pollutant(s) should only be ch	ecked if the "Reduced Pollution" line was	
Water:	☐ Ammonia ☐ BOD ☐ COD ☐ TSS ☐ OG ☐ Total Coliform ☐ D.O. ☐ Metals ☐ Cyanide ☐ Other	Air:	NOx SO2 Particulate Matter VOC Metals HAPs CO Other	
6. Did you provide gene Providing Compliance Yes			olicy on the Role of the EPA Inspector in	
7. Did you provide site Providing Compliance			he policy on the Role of the EPA Inspector	in
Yes				
8. Comments/Notes:	(optional)			